				50X1
COUNTR	Y Osechoslovakia	50X1	DATE DISTR. 31 Q	uq 63
SUBJECT	Bratislava-Vajno	ry Airfield	NO. OF PAGES	1
PLACE ACQUIRE	iD		NO. OF ENCLS. (LISTED BELOW)	50)
DATE ACQUIRE	D		SUPPLEMENT TO REPORT NO.	50)
DATE OF	INFORMATION			
	VIII (	IS UNEVALUATED INFORMATION		

1. Bratislava-Vajnory Airfield /4812N-1712E / was located /Encl. A / six to eight kilometers northeast of Bratislava and about 200 m. west of Dvornik /4812N-1713E /. It was situated 2 - 2½ km. north of the Bratislava-Ivanka Airfield /4810N-1712E / RC-1310 /. Dimensions of the field (which was a parallelogram in shape) were 1,000 m. southwest to northeast, and 900 m. southeast to northwest. The field's altitude (extracted from the pilot's handbook) was 133 m. above sea level.

50X1

50X1

Bratislava-Vajnory Airfield had formerly been used by CSA as the civilian airfield which serviced the city of Bratislava. In Fall 1951, upon the completion of the Bratislava-Ivanka Airfield, all CSA personnel and equipment were moved from Vajnory to Ivanka.

After that, Bratislava-Vajnory was taken over by the Air Force.

Bratislava-Vajnory was used as an Air Force Advanced Flight Training Base and that, "during good weather", to detour this airfield in order to avoid

an Air Force Advanced Flight Training Base and that, "during good weather", to detour this airfield in order to avoid possible collisions with the training aircraft. (Possibly it was a sub-section of the Advanced Flight Training School with head-quarters at Piestany Airfield 4835N-1751E

SECRET

SECURITY INFORMATION

<b>3.</b> 50X1 50X1	spr	airfield had a hard, level, grass surface in good condition. re was no artificial drainage system.	X1
50X1 50X1	spr	re was no artificial drainage system   GP+on +bo	
14	utn	ing thams this airfield was usually closed for two weeks. erwise weather was favorable for year-round flying.	
7	The	following were obstructions to the field	
50X1	a.	Bratislava Freight Yards, one quarter kilometer to the south west (20 m. obstruction).	
	b.	Lower Carpathian Range, 2½ k. to the northwest (642 m. above sea level).	
	c.	Village of Dvornik, 200 m. east, (30 m. obstruction).	
	d.	South corner of airfield, hangar ruins (10 m. obstruction).	
	e.	Airfield hangar / Encl. B, Pt.5_7(15 m. obstruction).	
	f.	Three chimneys, two kilometers south of field (40 m. obstructions).	
5.	The	field had the following technical facilities:	
50X1	a.	The radio transmitters and receivers, the D/F station, and radio beacon facilities which existed in 1950 were moved from this airfield to Bratislava-Ivanka in 1951 moved from Vajnory to Ivanka.	50
50X1	<b>b.</b>	at this field in 1950:	
		(1) ATC-DF-OKR-prijem (receive) (A/G) 333 Kcs, vys. (G/A) 336 Kc	38
		(2) ADC-DF-OKR-prijem (A/G) 322 Kcs, vys. (G/A) 320 Kcs.	
		(3) ADC- (HF fonie) Bratislava vez 3255 Kcs.	
		(4) RBn-OKR-391 Kes BCN.	
50X1	¢.	Telephones were available; teletype facilities which existed in 1950	
50X1	đ.	A weather station had been available in 1950 / building, Encl. B	
•	e.	Electricity was probably supplied from Bratislava.	
1	4	Portable landing lights were available upon request. Permanent perimeter lights existed in 1950. Obstructional lights were installed on all airfield buildings.	
50X1 <b>8</b>	g. :	In 1950 repair facilities for minor maintenance were available.	
6.	ne	ver observed AAA positions, electronic working devices, or ence of camouflage at the Bratislava-Vajnory Airfield.	

SECRET